



Differences of 3.00 vs IC

- EEPROM & jumpers removed
- No bankswitch logic
- Divider GAL replaced by 7474